CONSERVATION OF SANDSTONE MONUMENTS: A NEW APPROACH IN CONSOLIDATION TREATMENTS

M. Ludovico-Marques¹* and C. Chastre²

1: CICC/Department of Structures and Geotechnics Barreiro School of Technology Polytechnic Institute of Setúbal Rua Américo da Silva Marinho, 2839-001 Lavradio, Portugal e-mail: ludovicomarques@gmail.com web: http://www.itecons.uc.pt/projectos/cicc

> 2: UNIC/Department of Civil Engineering Faculty of Sciences and Technology Universidade NOVA de Lisboa Campus do Monte da Caparica, 2829-516 Caparica, Portugal e-mail: c-chastre@fct.unl.pt web: http://www.unic.fct.unl.pt

Keywords: Conservation, Sandstones, Sustainability, Ethyl silicates, Monuments.

Abstract Sandstones are very important in the building elements of world's historical and cultural heritage. The façades of St. Leonard's church in Atouguia da Baleia village in western region of Portugal are an outstanding example of the effect of alveolization on going for several centuries. In Middle ages there was an harbour and a sodium chloride rich environment near this church was responsible for this significant stone degradation pattern.

A new approach of consolidating products application on stone walls façades based on Karsten pipe using total head to allow full absorption of stone was followed.

Experimental research, based on physical and mechanical tests, was carried out on selected representative samples of a variety of sandstones on monuments treated with ethyl silicates in order to assess the effectiveness and harmfulness of these treatments.

The comparison of results between traditional immersion applications and Karsten pipe's based procedure on stone monument indicate the potential viability of this new approach when difficult conditions of consolidating products' absorption occurs on stone monuments.

4. CONCLUSIONS

A Karsten pipe using total head to allow full absorption of consolidating products on sandstone façades was used in conservation treatments.

Two ethyl silicates (TG and R) were selected and applied on sandstone specimens. The experimental study of physical and mechanical behaviour revealed slight harmful characteristics of the applications on C variety of sandstones and a good consolidation effect.

The comparison between immersion based procedure of applications and Karsten pipe's method on stone monuments indicate the potential viability of this new approach to obtain a good consolidation effect when difficult conditions of absorption occurs.

REFERENCES

- [1] ICOMOS International Scientific Committee for Stone, "Illustrated Glossary on Stone Deterioration Patterns", 2008.
- [2] M. Ludovico-Marques, "Contribution to the Knowledge of the Effect of Crystallization of Salts in the Weathering of Sandstones. Application to the Built Heritage of Atouguia da Baleia", PhD Thesis in Geotechnical Engineering, Specializing in Rock Mechanics, Universidade NOVA de Lisboa, Lisbon, 2008, (in Portuguese).
- [3] M. Ludovico-Marques, C. Chastre, "Effect of Salt Crystallization Ageing on the Compressive Behavior of Sandstone Blocks in Historical Buildings" *Engineering Failure Analysis*, vol. 26, pp. 247-257, 2012.
- [4] I. Evans, "Salt Crystallization and Rock Weathering: A Review" *Révue de Geomorphologie Dynamique*, vol. XIX(4), pp. 153-177, 1970.
- [5] C. Rodriguez-Navarro, E. Dohene, E. Sebastian, "Origins of Honeycomb Weathering: the Role of Salts and Wind" *Bulletin of Geological Society of America*, vol. 111, pp. 1250-1255, 1999.
- [6] RILEM, "Recommended Tests to Measure the Deterioration of Stone and to Assess the Effectiveness of Treatment Methods" *Matérieux et Constructions*, Bourdais-Dunoud, vol. 13 (75), pp. 175-253, 1980.
- [7] R. Folk (1974): Petrology of Sedimentary Rocks, Hemphill Publishing, Austin.
- [8] EN 1936, "Natural Stone Test Method-Determination of Real Density and Apparent Density, and of Total and Open Porosity", European Standard, 1999.
- [9] F. Pellerin, "La Porosimetrie au Mercure Appliquee a l' Etude Geotechnique des Sols et des Roches" Bulletin de Liaison des Laboratoires des Ponts et Chaussés, vol. 106, pp. 105-116, 1980.
- [10]NORMAL-29/88, "Misura dell' Indice di Asciugamento (Drying Index). Alterazioni dei Material Lapidei e Trattamenti Conservativi - Proposte per l'Unificazione dei Metodi Sperimentali di Studio e di Controllo", CNR–ICR, Roma, 1991.